SUBJECT: Carry-through Unit

41-3901. LA-6 Models.

DATE: March 23, 1934

## TO ALL OFFICES:


The camming surface of pawls 4307 and  $4307\frac{1}{4}$  and aligner cams 4325,4326, 4327, 4328, 4329, 4330 and 4331, have been altered to provide better action when the carriage dials operate.

New style pawls 4307 and 4307 can be used with the old style aligner cams.

The new style aligner cams can not be used with the old style pawls.

The instructions given on Plates 7 and 8 of Machine Service Bulletin No. 178 should be followed in preference to installing the new style parts. However, if satisfactory results can not be obtained the new style material should be installed.

When requisitioning these parts identify the aligner cams by adding xl to their numbers and the check pawls by adding N. S.



MACHINE PRIVATE BULLIANTE SELECTION generation: carry shrows Delt salohom bast ... dore...te Mr. B. P. James, Toledo. Ohio. The camer restrict of party and evel will kind to souther miner of . of whom which desired only norw advocation style file ont atthe bear of nun 47000 bon 7005 blood often wet who as tensition The new cryle aligner came out met be uned with the old atyle pawles. nisting equipment of the series of the control of the series of the seri When requisitioning thems purity lithurally the alleger come by adding at to thour numbers and the court powly by adding he be A STATE OF THE STA Implies. ANTENNA INCOME No. Newowsky stoll STATE GIVE